

EUROQUARTZ GROUP OBSOLESCENCE NOTIFICATION


SUMMARY				
PRODUCT CODE	(V)EMB572 , 53, 62, 42 series	ADVICE NUMBER	000035	
SPECIFICATION	TCXO/VCTCXO series			
REASON FOR OBSOLESCENCE	Start-up issues in certain applications			
CUSTOMER	All			
Raised By	Andy Treble	Date Raised	23 rd Oct 2017	Amended
Authorised By	Andy Treble – Quality Manager	Telephone	01460 230000	

DETAILS OF OBSOLESCENCE


The above ranges of product has been obsoleted due to problems in some applications when switching on and off in sequence.

ALTERNATIVE PARTS

The recommended alternative is the EMQF574 series of parts which has been designed as a drop in replacement.



EMB572



EMQF574

LAST TIME BUY DETAILS

None

Authorised Signature		Date	23 rd October 2017
-----------------------------	--	-------------	-------------------------------